



Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115

1/22





Fig. 1

Article Cleaning Apparatus 1000



Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115

3/22




Fig. 3

Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115

4/22




Fig. 4




Fig. 5

6/22




Fig. 6

Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115

7/22




Fig. 7

Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115

8/22




Fig. 8

Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115
9/22




Fig. 9

10/22




Fig. 10

11/22

Process 310
Selection




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15

800 Cycle Interruption Recovery Process




Fig. 16




Fig. 17

Ser.No.: 10/674,117
Inventor(s): T.J. Fyvie et al.
Docket No.: RD-29,557-5
Attorney: J. K. Testa
Telephone: (518) 387-5115
18/22




Fig. 18

19/22




Fig. 19




Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24